

| Release Date | Models   | OS            | SW Version | SW Release Note   |
|--------------|--|---------------|------------|---|
| 11/25/2024   | GW2485TC, GW2785TC, GW2790QT, GW3290QT, BL2485TC, BL2785TC, BL2790QT, BL3290QT, EX240, EX2710Q, EX2710U, EX3210U, EX270M, EX270QM, EX2710R, EX3210R, EX3410R, EX3415R, EX480UZ, EX251, EX271, EX271Q, EX271U, EX381U, EX321UX, EW3880R, EW2790U, EW3290U, EW2790Q, RD240Q, RD280U, RD320U, RD320UA, MA270U, MA320U, PD2506Q, PD2705U, PD2705UA, PD2706QN, PD2706U, PD2706UA, PD3205U, PD3205UA, PD3225U, PD3206U, SW242Q, SW272U, SW272Q | Windows 10/11 | V1.1.9.0   | 1. Support EW2790U, EW3290U, EW2790Q<br>2. Fix update fail issue caused by file path error(Unicode)                                       |
| 8/26/2024    | GW2485TC, GW2785TC, GW2790QT, GW3290QT, BL2485TC, BL2785TC, BL2790QT, BL3290QT, EX240, EX2710Q, EX2710U, EX3210U, EX270M, EX270QM, EX2710R, EX3210R, EX3410R, EX3415R, EX480UZ, EX251, EX271, EX271Q, EX271U, EX381U, EX321UX, EW3880R, RD240Q, RD280U, RD320U, RD320UA, MA270U, MA320U, PD2506Q, PD2705U, PD2705UA, PD2706QN, PD2706U, PD2706UA, PD3205U, PD3205UA, PD3225U, PD3206U, SW242Q, SW272U, SW272Q                            | Windows 10/11 | V1.1.7.0   | 1. Support EX251, EX271, EX271Q, EX271U, EX381U, MA270U, MA320U, RD320U, RD320UA, PD2706QN  |
| 5/30/2024    | GW2485TC, GW2785TC, GW2790QT, GW3290QT, BL2485TC, BL2785TC, BL2790QT, BL3290QT, EX240, EX2710Q, EX2710U, EX3210U, EX270M, EX270QM, EX2710R, EX3210R, EX3410R, EX3415R, EX480UZ, EX321UX, EW3880R, RD240Q, RD280U, PD2506Q, PD2705U, PD2705UA, PD2706U, PD2706UA, PD3205U, PD3205UA, PD3225U, PD3206U, SW242Q, SW272U, SW272Q   | Windows 10/11 | V1.1.5.0   | 1. Support new model EX321UX  |
| 5/6/2024     | EX480UZ, EX3210U, EX2710U, EX2710Q, EX270QM, EX3410R, EX3415R, EX240, EX270QM, EX2710R, EX3210R, EW3880R, GW2485TC, GW2785TC, GW2790QT, GW3290QT, BL2485TC, BL2785TC, BL2790QT, BL3290QT, PD2506Q, PD2705U, PD2705UA, PD2706UA, PD3205U, PD3205UA, SW272U, SW272Q, RD240Q, SW242Q, PD3225U   | Windows 10/11 | V1.1.2.0   | 1. Support new model RD240Q, SW242Q, PD3225U<br>2. Fix EX3210U FW update fail issue   |
| 3/17/2023    | EX480UZ, EX3210U, EX2710U, EX2710Q, EX270QM, EX3410R, EX3415R, EX240, EX270QM, EX2710R, EX3210R, EW3880R, GW2485TC, GW2785TC, GW2790QT, GW3290QT, BL2485TC, BL2785TC, BL2790QT, BL3290QT, PD2506Q, PD2705U, PD2705UA, PD2706UA, PD3205U, PD3205UA, SW272U, SW272Q  | Windows 10/11 | V1.0.5.2   | 1. Fix bug for EX3210U FW V04 and V05 update fail<br>2. Optimize the flow to recognize USB hub<br>3. Optimize About page display behavior |