

Release Date	Models	OS	Version	Release Note
2023/6/16	P03220U, P02725U P03420Q	macOS 13 or later	V10.0.0	<p><b>1. First release</b></p> <p>Support all Mac devices with the Intel® M series chips.</p> <p><b>2. Limitation:</b></p> <p>Mac Mini/Macbook M1/M2 Pro &amp; Macbook M1/M2 Max &amp; Mac Studio M1 Max and M1 Ultra cannot sync with the monitor when using HDMI Port. We recommend connecting the monitor via Thunderbolt 3 (USB-C) cable or USB-C to DisplayPort cable.</p>
2023/8/28	P03220U, P02725U P03420Q	macOS 13 or later	V10.0.1	<p><b>Fixed Issue:</b></p> <p>1. Fixed downloading correctly from OTA that need to download v10.0.1.1 for further OTA.</p> <p><b>2. Limitation:</b></p> <p>Mac Mini/Macbook M1/M2 Pro &amp; Macbook M1/M2 Max &amp; Mac Studio M1 Max and M1 Ultra cannot sync with the monitor when using HDMI Port. We recommend connecting the monitor via Thunderbolt 3 (USB-C) cable or USB-C to DisplayPort cable.</p>
2023/10/24	P03220U, P02725U P03420Q, P02706U(A) P02705U(A), P03205U(A) P02506Q, P02705Q	macOS 13 or later	V10.0.5	<p><b>Fixed Issue:</b></p> <p>1. When turning on Auto Pivot, the screen is turned to portrait mode without rotating the physical monitor on the M2 series.</p> <p><b>Limitation:</b></p> <p>(1) Mac Mini/Macbook M1/M2 Pro &amp; Macbook M1/M2 Max &amp; Mac Studio M1 Max and M1 Ultra cannot sync with the monitor when using HDMI Port. We recommend connecting the monitor via Thunderbolt 3 (USB-C) cable or USB-C to DisplayPort cable.</p> <p>(2) Display Pilot 2 can't control each monitors well when using Display Pilot 2 on two or more of the same models produced on the same date.</p>
2023/12/19	P03220U, P02725U P03420Q, P02706U(A) P02705U(A), P03205U(A) P02506Q, P02705Q	macOS 13 or later	V10.0.7	<p><b>Fixed Issue:</b></p> <p>1. Fixed the two same-model monitors, which were produced on the same day that the Apple M series chip couldn't recognize each one.</p> <p>2. Fixed the software dimming error when enabling software dimming caused the MacBook Retina display to dim.</p> <p><b>Limitation:</b></p> <p>1. Mac Mini/Macbook M1/M2 Pro &amp; Macbook M1/M2 Max &amp; Mac Studio M1 Max and M1 Ultra cannot sync with the monitor when using HDMI Port. We recommend connecting the monitor via Thunderbolt 3 (USB-C) cable or USB-C to DisplayPort cable.</p>
2024/1/18	P03220U, P02725U P03420Q, P02706U(A) P02705U(A), P03205U(A) P02506Q, P02705Q P03225U, P03206U	macOS 13 or later	V10.0.9	<p>Adding support models P03225U and P03206U</p> <p><b>Limitation:</b></p> <p>1. Mac Mini/Macbook M1/M2 Pro &amp; Macbook M1/M2 Max &amp; Mac Studio M1 Max and M1 Ultra cannot sync with the monitor when using HDMI Port. We recommend connecting the monitor via Thunderbolt 3 (USB-C) cable or USB-C to DisplayPort cable.</p>
2024/2/1	P03220U, P02725U P03420Q, P02706U(A) P02705U(A), P03205U(A) P02506Q, P02705Q P03225U, P03206U, R0240Q	macOS 13 or later	V11.0.0	<p><b>1. First release of Display Pilot 2 for Programming series.</b></p> <p>Adding support model R0240Q</p> <p><b>2. Limitation:</b></p> <p>Mac Mini/Macbook M1/M2 Pro &amp; Macbook M1/M2 Max &amp; Mac Studio M1 Max and M1 Ultra cannot sync with the monitor when using HDMI Port. We recommend connecting the monitor via Thunderbolt 3 (USB-C) cable or USB-C to DisplayPort cable.</p>
2024/5/2	P03220U, P02725U, P03420Q, P02706U(A), P02705U(A), P03205U(A), P02506Q, P02705Q, P03225U, P03206U, R0240Q, R0280U, R0280UA	macOS 13 or later	V11.0.0	<p><b>PD series:</b></p> <p>1. Fix the issue that iC3sync can't work when the system can't get the right direction</p> <p>2. Fix the issue that it can't be updated by OTA in China.</p> <p><b>Limitation:</b></p> <p>Some Mac devices cannot sync with BenQ PD series monitors when using the HDMI port. Thus, we recommend connecting the monitor via the Thunderbolt 3 (4 (USB-C) cable or USB-C to DisplayPort cable when using Display Pilot 2 as part of your workflow</p> <p><b>RD series:</b></p> <p>1. 1st release of Display Pilot 2 for Programming series.</p> <p>2. Supported models: R0240Q/R0280U/R0280UA/R0320U/R0320UA</p> <p><b>Limitation:</b></p> <p>The Focus feature is supported only on macOS 12 and above.</p>
2024/8/26	P03220U, P02725U, P03420Q, P02706U, P02706UA, P02705U, P02705UA, P03205U, P03205UA, P02506Q, P02705Q, P02725U, P03206U, R0240Q, R0280U, R0280UA, R0320U, R0320UA, MA270U, MA320U	macOS 13 or later	V12.0.0	<p><b>Fixed Issues:</b></p> <ul style="list-style-type: none"> <li>Fixed text overlapping due to text space limitations in some languages</li> <li>Support the HDMI port of Mac devices with the M series chip</li> <li>Software dimming brightness adjusted</li> </ul> <p><b>RD Series:</b></p> <p>1. Upgraded Display Pilot 2 for Programming series, with support for more new functions.</p> <p>Supported models: R0240Q/R0280U/R0280UA/R0320U/R0320UA</p> <p><b>Limitation:</b> The Focus feature is supported only on macOS 12 and above.</p> <p><b>MA Series:</b></p> <p>1. 1st release of Display Pilot 2 for Monitors for Macbook series</p> <p>Supported models: MA270U/MA320U</p>
2024/10/14	P03220U, P02725U, P03420Q, P02706U, P02706UA, P02705U, P02705UA, P03205U, P03205UA, P02506Q, P02705Q, P02725U, P03206U, R0240Q, R0280U, R0280UA, R0320U, R0320UA, MA270U, MA320U	macOS 13 or later	V13.0.0	<p><b>Fixed Issues:</b></p> <ul style="list-style-type: none"> <li>Fixed log issues when adjusting settings such as brightness, volume, or active functions.</li> </ul> <p><b>PD Series:</b></p> <p>1. Permission adjustments for conflicts with Palette Master Ultimate iC3sync feature.</p> <p>2. HDR functionality added to the following models: P02705Q, P02506Q, P03420Q, and P02706Q</p> <p>3. Added new support model: P02705QN</p>
2024/11/1	P03220U, P02725U, P03420Q, P02706U(A), P02705U(A), P03205U(A), P02506Q, P02705Q, P03225U, P03206U, P02706QN, R0240Q, R0280U, R0280UA, R0320U, R0320UA, MA270U, MA320U, EW2790U	macOS 13 Ventura or above	v14.0.0	<p><b>MA Series:</b></p> <p>1. Added brightness gradual transition effect when Brightness Sync=On and B1+ Gen2 =On.</p> <p>2. Removed the HDR option from the Application Color Mode menu, and when HDR=On, the Application Color Mode function will be temporarily disabled.</p> <p>3. Fixed issue where audio mode could not be selected in FocusSync.</p> <p><b>EW Series:</b></p> <p>1. Support new model EW2790U.</p> <p>2. Add DIT series new features: Scenario Assistant, Pomodoro Timer, and Audio Equalizer.</p>
2024/11/22	P03220U, P02725U, P03420Q, P02706U(A), P02705U(A), P03205U(A), P02506Q, P02705Q, P03225U, P03206U, P02706QN, R0240Q, R0280U, R0280UA, R0320U, R0320UA, MA270U, MA320U, EW2790U	macOS 13 Ventura or above	v14.5.0	<p><b>MA Series:</b></p> <p>1. Fixed random crash issue after waking up.</p> <p>2. Fixed low brightness issue when switching color mode under Brightness Sync is on.</p> <p><b>RD Series:</b></p> <p>1. Added new features: Color Weakness and Resolution Bar</p> <p>Supported models: R0240Q, R0280U, R0280UA, R0320U, R0320UA</p> <p>2. Fixed minor issues related to the following functions: Focus, HDR, &amp; Flow</p>
2025/1/2	P03220U, P02725U, P03420Q, P02706U(A), P02705U(A), P03205U(A), P02506Q, P02705Q, P03225U, P03206U, P02706QN, R0240Q, R0280U, R0280UA, R0320U, R0320UA, MA270U, MA320U, EW2790U, EW3290U, EW2790Q	macOS 13 Ventura or above	v15.0.0	<p>1. Fixed occasional disconnection, display not being detected or functions fail issues after laptop reset, sleep, or lid open/close.</p> <p>2. Supported macOS 15 to redirect access permission buttons to the Mac System Settings page.</p> <p>3. Fixed occasional failures of Keyboard control when using external keyboards.</p> <p><b>MA Series:</b></p> <p>1. Added MA series new feature: Device Color Sync.</p> <p>2. Added brightness gradual transition effect when when B1+ Gen2 is turned on.</p> <p>3. Added explanation text for B1+ Gen2.</p> <p>4. Fixed flicker screen issues when switching between Mac desktops</p> <p>5. Changed rules that the "new display(s) detected" message would not appear if the current device setup remains unchanged.</p> <p><b>PD Series:</b></p> <p>1. Support new models P03226Q, P02730S.</p> <p>2. Add PD series new features on P03226Q, P02730S: Hotkey/Puck control setting</p> <p><b>RD Series:</b></p> <p>RD function optimization: HDR, &amp; Shortcuts</p> <p><b>EW Series:</b></p> <p>1. Support new models EW3290U, EW2790Q</p> <p>2. Add new features Scenario Assistant (beta) and Shortcuts</p>
2025/2/5	P03220U, P02725U, P03420Q, P02706U(A), P02705U(A), P03205U(A), P02506Q, P02705Q, P03225U, P03206U, P02706QN, P03226Q, P02730S, R0240Q, R0280U, R0280UA, R0320U, R0320UA, MA270U, MA320U, EW2790U, EW3290U, EW2790Q	macOS 13 Ventura or above	v15.0.0	<p>1. Fixed an issue where the software sometimes fails to start or requires a restart to function properly.</p> <p>2. Fixed a malfunction in Adobe software when Keyboard Control was enabled.</p> <p>3. Fixed a volume adjustment failure and an issue where the monitor name incorrectly displayed as "DisplayPort" in the audio output menu on some Intel Mac models.</p> <p>4. Fixed a volume adjustment issue where only one monitor could be controlled when two were connected.</p>
2025/2/26	P03220U, P02725U, P03420Q, P02706U, P02706UA, P02705U, P03205U, P02705UA, P02506Q, P02705Q, P03225U, P03206U, P02706QN, P03226Q, P02730S, R0240Q, R0280U, R0280UA, R0320U, R0320UA, MA270U, MA320U, EW2790U, EW3290U, EW2790Q	macOS 13 Ventura or above	v15.0.0	<p>1. Fixed a malfunction in Adobe software when Keyboard Control was enabled.</p>
2025/3/13	P03220U, P02725U, P03420Q, P02706U, P02706UA, P02705U, P03205U, P02705UA, P02506Q, P02705Q, P03225U, P03206U, P02706QN, P03226Q, P02730S, R0240Q, R0280U, R0280UA, R0320U, R0320UA, MA270U, MA320U, EW2790U, EW3290U, EW2790Q	macOS 13 Ventura or above	v16.0.0	<p><b>MA Series:</b></p> <p>1. Added color profiles of MFP M4 series, iPad and iPhone for Device Color Sync function.</p> <p>2. Fixed an issue where HDRPI was not supported when setting the monitor resolution via the Resolution slider.</p> <p>3. Fixed a crash issue caused by unplugging the cable while Brightness Sync was in progress.</p>
2025/4/9	P03220U, P02725U, P03420Q, P02706U, P02706UA, P02705U, P03205U, P02705UA, P02506Q, P02705Q, P03225U, P03206U, P02706QN, P03226Q, P02730S, R0240Q, R0280U, R0280UA, R0320U, R0320UA, MA270U, MA320U, EW2790U, EW3290U, EW2790Q	macOS 13 Ventura or above	v16.0.0	<p>Fixed issues including update failures, repeated update prompts, failure to restart automatically after updating, and incorrect detection as a "Non-supported monitor".</p> <p><b>Limitation:</b></p> <p>Upgrading from an older version may fail. If this happens, please try deleting all the "bXXPackage.dmg" file from the Downloads folder, then run the "b6.2.0.dmg" file to complete the installation.</p>
2025/5/9	P03220U, P02725U, P03420Q, P02706U, P02706UA, P02705U, P03205U, P02705UA, P02506Q, P02705Q, P03225U, P03206U, P02706QN, P03226Q, P02730S, PV3200U R0240Q, R0280U, R0280UA, R0320U, R0320UA, MA270U, MA320U, EW2790U, EW3290U, EW2790Q	macOS 13 Ventura or above	v16.5.0	<p>1. Fixed an issue of the program logging when entering the audio setting</p> <p>2. Adjusted Device ColorSync and Scenario (a)/b/a.</p> <p><b>PV Series</b></p> <p>1. Support new model PV3200U.</p> <p>2. Add new feature Eco-locking</p>
2025/6/20	P03220U, P02725U, P03420Q, P02706U, P02706UA, P02705U, P03205U, P02705UA, P02506Q, P02705Q, P03225U, P03206U, P02706QN, P03226Q, P02730S, PV3200U R0240Q, R0280U, R0280UA, R0320U, R0320UA, MA270U, MA320U, EW2790U, EW3290U, EW2790Q	macOS 13 Ventura or above	v16.7.0	<p>1. Fixed the issue where logging in with WhatsApp does not respond.</p>