

Release Date	Models	OS	SW Version	SW Release Note
2025/6/9	GW Series: GW2485TC, GW2785TC, GW2486TC, GW2786TC, GW2790QT, GW3290QT BL Series: BL2485TC, BL2785TC, BL2486TC, BL2786TC, BL2790QT, BL3290QT EX Series: EX240, EX2710Q, EX2710U, EX3210U, EX270M, EX270QM, EX2710R, EX3210R, EX3410R, EX3415R, EX480UZ, EX25I, EX27I, EX271Q, EX27IU, EX381U, EX321UX EW Series: EW3880R, EW2790U, EW3290U, EW2790Q RD Series: RD240Q, RD280U, RD280UA, RD320U, RD320UA MA Series: MA270U, MA320U PD Series: PD2506Q, PD2705U, PD2705UA, PD2706U, PD2706UA, PD3205U, PD3205UA, PD3225U, PD3206U, PD2730S, PD3226G SW Series: SW242Q, SW272U, SW272Q PV Series: PV3200U	Windows 10/11	V1.113.0	1. Add new function: Current FW version, Log ID upload
2025/2/26	GW Series: GW2485TC, GW2785TC, GW2486TC, GW2786TC, GW2790QT, GW3290QT BL Series: BL2485TC, BL2785TC, BL2486TC, BL2786TC, BL2790QT, BL3290QT EX Series: EX240, EX2710Q, EX2710U, EX3210U, EX270M, EX270QM, EX2710R, EX3210R, EX3410R, EX3415R, EX480UZ, EX25I, EX27I, EX271Q, EX27IU, EX381U, EX321UX EW Series: EW3880R, EW2790U, EW3290U, EW2790Q RD Series: RD240Q, RD280U, RD280UA, RD320U, RD320UA MA Series: MA270U, MA320U PD Series: PD2506Q, PD2705U, PD2705UA, PD2706U, PD2706UA, PD3205U, PD3205UA, PD3225U, PD3206U, PD2730S, PD3226G SW Series: SW242Q, SW272U, SW272Q PV Series: PV3200U	Windows 10/11	V1.111.0	1. Support PV3200U, PD2730S, PD3226G
2024/11/25	GW Series: GW2485TC, GW2785TC, GW2486TC, GW2786TC, GW2790QT, GW3290QT BL Series: BL2485TC, BL2785TC, BL2486TC, BL2786TC, BL2790QT, BL3290QT EX Series: EX240, EX2710Q, EX2710U, EX3210U, EX270M, EX270QM, EX2710R, EX3210R, EX3410R, EX3415R, EX480UZ, EX25I, EX27I, EX271Q, EX27IU, EX381U, EX321UX EW Series: EW3880R, EW2790U, EW3290U, EW2790Q RD Series: RD240Q, RD280U, RD280UA, RD320U, RD320UA MA Series: MA270U, MA320U PD Series: PD2506Q, PD2705U, PD2705UA, PD2706U, PD2706UA, PD3205U, PD3205UA, PD3225U, PD3206U SW Series: SW242Q, SW272U, SW272Q	Windows 10/11	V1.1.9.0	1. Support EW2790U, EW3290U, EW2790Q 2. Fix update fail issue caused by file path error(Unicode)
2024/8/13	GW Series: GW2485TC, GW2785TC, GW2486TC, GW2786TC, GW2790QT, GW3290QT BL Series: BL2485TC, BL2785TC, BL2486TC, BL2786TC, BL2790QT, BL3290QT EX Series: EX240, EX2710Q, EX2710U, EX3210U, EX270M, EX270QM, EX2710R, EX3210R, EX3410R, EX3415R, EX480UZ, EX25I, EX27I, EX271Q, EX27IU, EX381U, EX321UX EW Series: EW3880R RD Series: RD240Q, RD280U, RD280UA, RD320U, RD320UA MA Series: MA270U, MA320U PD Series: PD2506Q, PD2706QN, PD2705U, PD2705UA, PD2706U, PD2706UA, PD3205U, PD3205UA, PD3225U, PD3206U SW Series: SW242Q, SW272U, SW272Q	Windows 10/11	V1.1.7.0	1. Support EX25I, EX27I, EX271Q, EX27IU, EX381U, MA270U, MA320U, RD320U, RD320UA, PD2706QN
2024/5/30	GW Series: GW2485TC, GW2785TC, GW2486TC, GW2786TC, GW2790QT, GW3290QT BL Series: BL2485TC, BL2785TC, BL2486TC, BL2786TC, BL2790QT, BL3290QT EX Series: EX240, EX2710Q, EX2710U, EX3210U, EX270M, EX270QM, EX2710R, EX3210R, EX3410R, EX3415R, EX480UZ, EX271UX EW Series: EW3880R RD Series: RD240Q, RD280U, RD280UA PD Series: PD2506Q, PD2705U, PD2705UA, PD2706U, PD2706UA, PD3205U, PD3205UA, PD3225U, PD3206U SW Series: SW242Q, SW272U, SW272Q	Windows 10/11	V1.1.5.0	1. Support new model EX321UX
2024/5/6	GW Series: GW2485TC, GW2785TC, GW2790QT, GW3290QT BL Series: BL2485TC, BL2785TC, BL2790QT, BL3290QT EX Series: EX240, EX2710Q, EX2710U, EX3210U, EX270M, EX270QM, EX2710R, EX3210R, EX3410R, EX3415R, EX480UZ EW Series: EW3880R RD Series: RD240Q, RD280U, RD280UA PD Series: PD2506Q, PD2705U, PD2705UA, PD2706U, PD2706UA, PD3205U, PD3205UA, PD3225U, PD3206U SW Series: SW242Q, SW272U, SW272Q	Windows 10/11	V1.1.2.0	1. Support new model PD3225U, PD3206U, RD240Q, RD280U, RD280UA, SW242Q 2. Fix EX3210U FW update fail issue
2023/3/17	GW Series: GW2485TC, GW2486TC, GW2785TC, GW2786TC, GW2790QT, GW3290QT BL Series: BL2485TC, BL2486TC, BL2785TC, BL2786TC, BL2790QT, BL3290QT EX Series: EX240, EX2710Q, EX2710U, EX3210U, EX270M, EX270QM, EX2710R, EX3210R, EX3410R, EX3415R, EX480UZ EW Series: EW3880R PD Series: PD2506Q, PD2705U, PD2705UA, PD2706U, PD2706UA, PD3205U, PD3205UA SW Series: SW272U, SW272Q	Windows 10/11	V1.0.5.2	1. Fix bug for EX3210U FW V04 and V05 update fail 2. Optimize the flow to recognize USB hub 3. Optimize About page display behavior